






Packing Procedure For 8x10 60B WBGA Product

Table of Contents

(1) PACKING PROCEDURE	1
(2) PACKAGING QUANTITY.....	2
(3) SPECIFICATION OF SHIPPING BOX	4
(4) PACKING DRAWING	7

(1) Packing Procedure -1

■ Packing procedure for Tray



(2) Packaging Quantity


■ Quantity of Container

The quantity for each container is described as below table for reference.

Pkg. Type	Packing Qty	Dry Bag	Inner Box	Outer Box
8*10 60 Ball-WBGA	264 ea/Tray	10 Tray (2640 ea)	1 Dry Bag (2640 ea)	6 Inner Boxes (15840 ea)

(3) Specification of Shipping Box -1


■ Tray Outer Box Drawing



Tolerance: $\pm 5\text{mm}$

(3) Specification of Shipping Box -2


■ Tray Outer Box Drawing-buffer



Tolerance: $\pm 3\text{mm}$

(3) Specification of Shipping Box -2

■ Tray Inner Box Drawing



Tolerance: $\pm 3\text{mm}$



(4) Packing Drawing -1

■ Tray Drawing of 8x10 60B-WBGA

